

**ADDITIONAL COMMISSIONER OF POLICE,
MOTOR TRANSPORT SECTION, MUMBAI-400 008
QUOTATION NOTICE**

Ref.No. Ref.No.MUMBAI POLICE/MT/QUOTATION(LAUNCH-8)/2024-25.

Date:-24/05/2024

The Additional Commissioner of Police, Motor Transport, Mumbai - 400008 invites sealed Quotations for repair of BOAT ENGINE & EQUIPMENT from Suppliers of Mumbai City and suburban area i.e. within the Municipal limit of Greater Mumbai.

Following BOAT REPAIR OF ENGINE is required for **Mumbai Police Launch 8** Bidders are requested to quote their lowest offer in Schedule - 'A' attached herewith.

The Sealed quotations should be dropped in Quotation Box before 31/05/2024 at 11:00 hrs. At the office of the, Asstt .Commissioner of Police (5) Motor Transport Section, Shepherd Road, Nagpada, Mumbai-400008.

The Quotations will be opened on date 01/06/2024 at 11:00 hrs, at office of the, Additional Commissioner of Police, Motor Transport Section, Shepherd Road, Nagpada, Mumbai-400008.

Bidders are at liberty to be present or authorised their representative to be present at the opening of Quotation at the time, date & place specified as above.

Terms & Conditions for supply

1. Spare parts should be supplied by bidders on demand only.
2. Spare parts used/destroyed in test will not be returned and no payment made thereof.
3. **All repair works which will be carried out on engine and auxiliaries along with fitment of new equipment should be supported with warranty/Guarantee period.**
4. Prices quoted should be Total cost inclusive of GST or duties such as Excise duty, Custom duty, Surcharge if any which the supplier is require to pay to the manufacturer should also include in Price. The bills /invoices of material/Goods purchased /received will be processed after the material/Goods are inspected by our Kit Committee and found acceptable. In case the material is rejected the Bidder/Supplier has to collect the material from our Launch Section at his own cost, and replace by a fresh supply. The Bills of an item rejected and not replaced by a fresh supply will not be processed for payment.
5. **The Additional Commissioner of Police, Motor Transport, Mumbai – 400 008 reserves the right to accept or reject any or all the part of Quotations without assigning any reason.**
6. Price will not exceed then MRP Price.
7. Price quoted will be fixed for One year i.e. up to Validity of Quotation and no further changes will be accepted.

8. In Case of any changes in GST, revised tax charges will be applicable.
9. Bidding documents can be seen, downloaded & submitted from Date 24/05/2024 to 31/05/2024.
10. Bidder should submit his Quotation with his Authorised Letter Head mentioning GST no. along with copy of PAN card.
11. If possible, quotations will be opened offline on Date 01/06/2024. Hrs. 11:00 at The Office of Additional Commissioner of Police, Motor Transport Section, Shepherd Road, Nagpada, Mumbai - 400 008.

(Sachin Badhe)
Deputy Commissioner of Police (1)
Addl. Charge. Addl. Commissioner of Police,
Motor Transport, Mumbai.

Annexure 'A'

REPAIRING OF EVINRUDE ENGINES AND ASSOCIATED EQUIPMENTS OF **MUMBAI 8 BOAT**
INCLUDING WITH SPARES AND MATERIALS, LA OUR CGARGES.

Name of Bidder: M/s

GST No.....

Sr. No (1)	Description of Work / Item (2)	UNIT (3)	Basic Price(4)	GST (5)	Total Cost (6)
1	Port Evinrude engine of boat gets overheated while exploiting above 2500 RPM. Suspect injector/coil, sea water system, Instrumentation malfunctioning. needs to be inspected/ repaired	Nos			
2	02 Nos. of Evinrude engines of boat gets over racing, vibrating and shutting down at idle. Suspect injector/coil, sea water system, Instrumentation malfunctioning. Defect needs to be repaired.	Nos			
3.	02 Nos. trim units of boats malfunctioning. Suspect oil seal worn-out. Units to be overhauled/repared/replaced	Nos			
4.	Reverse gear of Starboard engine malfunctioning. Starboard Gear box to be overhauled/repared.	Nos			
5.	Abnormal sound from Port gear box. Port gear box needs to be inspected/ repair	Nos			
6.	Speedometer gauge not working	Nos			
7.	Wiper nozzle not working	Nos			
8.	Sunroof glass is damaged. Needs to be changed	Nos			
9.	I com Digital Throttling and shifting (DTS) stbd side actuator falls freely while exploiting the engine which leads to abrupt increase in RPM. Defect needs to be rectified	APS			
10.	Steering oil leaking from steering ram seal which leads to sluggish operation. Defect to be rectified	APS			
11.	All electrical navigation lighting not working properly. Defect to be rectified	Nos			
12	Water leaking from Port side fender collar securing bolts. Needs to be repair	APS			

Supplier's Signature & Seal