ADDITIONAL COMMISSIONER OF POLICE, MOTOR TRANSPORT SECTION, MUMBAI-400 008

QUOTATION NOTICE / FIRST EXTENSION

Ref.No MUMBAI POLICE/MT/QUOTATION (LAUNCH – 8)/2024-2025. 24/05/2024

The Additional Commissioner of Police, Motor Transport, Mumbai - 400008 invites sealed Quotations for repair of **BOAT ENGINE & EQUIPMENT** from repair contractor of Mumbai City and suburban area i.e. within the Municipal limit of Greater Mumbai.

Following BOAT REPAIR OF ENGINE is required for **Mumbai Police Launch 8** Bidders are requested to quote their lowest offer in Schedule – Annexure 'A' attached herewith.

The Sealed quotations should be dropped in Quotation Box before 07/06/2024 at 11:00 hrs. At the office of the, Asstt .Commissioner of Police (5) Motor Transport Section, Shepherd Road, Nagpada, Mumbai-400008.

The Quotations will be opened on date 08 /06 /2024 at 11:00 hrs, at office of the, Additional Commissioner of Police, Motor Transport Section, Shepherd Road, Nagpada, Mumbai-400008.

Bidders are at liberty to be present or authorised their representative to be present at the opening of Quotation at the time, date &place specified as above.

Terms & Conditions for supply

- 1. Spare parts should be supplied by bidders on demand only.
- 2. Spare parts used/destroyed in test will not be returned and no payment made thereof.
- 3. All repair works which will be carried out on engine and auxiliaries along with fitment of new equipment should be supported with warranty/Guarantee period.
- 4. Prices quoted should be Total cost inclusive of GST or duties such as Excise duty, Custom duty, Surcharge if any which the supplier is required to pay to the manufacturer should also include in Price. The bills /invoices of material/Goods purchased /received will be processed after the material/Goods are inspected by our Kit Committee and found acceptable. In case the material is rejected the Bidder/Supplier has to collect the material from our Launch Section at his own cost, and replace by a fresh supply. The Bills of an item rejected and not replaced by a fresh supply will not be processed for payment.
- 5. The Additional Commissioner of Police, Motor Transport, Mumbai $-400\,008$ reserves the right to accept or reject any or all the part of Quotations without assigning any reason.
- 6. Price will not exceed than MRP Price.
- 7. Price quoted will be fixed for One year i.e. up to Validity of Quotation and no further changes will be accepted.
- 8. In Case of any changes in GST, revised tax charges will be applicable.
- 9. Bidding documents can be seen, downloaded & submitted from Date 01/06/2024 to 07/06/2024.

- 10. Bidder should submit his Quotation with his Authorised Letter Head mentioning GST no. along with copy of PAN card.
- 11. If possible, quotations will be opened offline on Date.08/06/2024 Hrs. 11:00 at The office of Additional Commissioner of Police, Motor Transport Section, Shepherd Road, Nagpada, Mumbai 400 008.

(Sachin Badhe)
Deputy Commissioner of Police (1)
Addl. Charge. Addl. Commissioner of Police,
Motor Transport, Mumbai.

Annexure 'A'

REPAIRING OF EVINRUDE ENGINES AND ASSOCIATED EQUIPMENTS OF MUMBAI - 4 BOAT INCLUDING WITH SPARES AND MATERIAL, LABOUR CHARGES

Name of Bidder: M/s	
GST No	

Sr. No	Description of Work / Item	UNIT	Basic Price	GST	Total Cost
(1)	(2)	(3)	(4)	(5)	(6)
1	02 nos of Evinrude engines of boat gets overheated while exploiting above 2500 RPM. Suspect injector/coil, sea water system, Instrumentation malfunctioning. needs to be inspected/repaired.	Nos			
2	Starboard engine vibrates and shutting off automatically. Suspect injector/coil, air system, instrumentation, malfunctioning. needs to be inspected/ repaired/ replaced.	Nos			
3	O2 nos trim units of boats malfunctioning. Suspect oil seal wornout. Units to be overhauled/repaired/replaced	Nos			
4	Water ingress observed in 02 nos of gear boxes of boat. Suspect oil seal and other component wornout/damaged. Units to be overhauled/repaired.	Nos			
5	Starting trouble observed in 02 nos of Evinrude engines. Suspect starter of 02 engine malfunctioning interminently. Starters to be overhauled/repaired/replaced	Nos			
6	Reverse gear of Port engine interminently malfunctioning. Port Gear box to be overhauled/repaired.	Nos			
7	Steering system found sluggish operation. System to be repair.	APS			
8	All navigation lighting & electrical equipments to be check for its operationality. Required repair/replace.	APS			
9	Fuel tank sounding cap found damaged required to be replaced	Nos			

Supplier's Signature & Seal